ECS Configuration C	nange Request				Page 1 of		Paç	ge(s)	
1. Originator	2. Log Date:	3. CCR #:		4. Rev:	5. Tel:	6	6. Rm #:	7. Dept.	
Robert Cole	6/13/02	02-0484		_	301-925-0799	2	2110C	SE/HW	
8. CCR Title: Install Santricity 8.00.G2.01 on p0sas01 for PSR									
9. Originator Signature/Date			10. Class		11. Type:	12. N	12. Need Date: 6/30/02		
Robert Cole /s/ 6/13/02			IN		CCR	CR			
13. Office Manager Signature/Date Jim Mather /s/ 6/13/02						Block 27).	f "Emergency"		
· ·			7. Schedule mpact:		18. CI(s) A	18. CI(s) Affected:SAN			
19. Release Affected by this Change: 20. Date due N/A				None - Under 100K					
22. Source Reference: ☐NCR (attach) ☐Action Item ☐Tech Ref. ☐GSFC ☐Other:									
23. Problem: (use additional Sheets if necessary) The new D178 controllers require a new storage management COTS product, Santricity version 8.00.G2.01. In oder to PSR this product, it needs to be installed and tested on p0sas01 as the PVC is the only test environment with a compatible controller.									
24. Proposed Solution: (use additional sheets if necessary) Install and test Santricity 8.00.G2.01 on p0sas01. This COTS product will replace SYMplicity Storage Manager 7.10.GG.02.									
25. Alternate Solution: (use additional sheets if necessary)									
26. Consequences if Change(s) are not approved: (use additional sheets if necessary) The PSR cannot be completed in time for the Synergy III hardware installs sheduled starting in mid July.									
27. Justification for Emergency (If Block 15 is "Emergency"):									
28. Site(s) Affected: ☐EDF ☐PVC ☐VATC ☐EDC ☐ GSFC ☐LaRC ☐NSIDC ☐SMC ☐AK ☐JPL ☐EOC ☐ IDG Test Cell ☐Other									
29. Board Comments:				30. V	Vork Assigned T	o: 3	31. CCR C	Closed Date:	
32. EDF/SCDV CCB Chair (Otai Harley /s/ 6/19/02	Sign/Date): Di	isposition: A	pproved	App/C	om. Disapproved	ltiW b	:hdraw Fw	vd/ESDIS	
33. M&O CCB Chair (Sign/I	Date): Di	isposition: Ap	oproved wd/ECS	App/Co	m. Disapproved	l With	hdraw Fwo	d/ESDIS ERB	
34. ECS CCB Chair (Sign/D	Date): Dis	sposition: Ap	proved vd/ESDI	• •	m. Disapproved	l With	hdraw Fw	vd/ESDIS ERB	